

Final Reclamation Inspection

November 1st, 2023

Operator: Logos Operating LLC - 10679

Location ID: 385734

Inspection Document #: 714000109

La Plata County, CO

Township: SWNW 13 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9 35
Location ID: 385734



Photo 1. View of the project area taken from the southern edge facing north. Horse corral on project area appears to be hindering final reclamation.

Inspection Photos
Location Name: Bondad 33-9 35
Location ID: 385734



Photo 2. View of western cutslope taken from the southern edge facing north. Cut slope and flat well pad disturbance suggest the project area has not been recontoured.

Inspection Photos
Location Name: Bondad 33-9 35
Location ID: 385734



Photo 3. View of the project area taken from the northeast corner facing center. Note: additional unused well head marker remains on location.

Inspection Photos
Location Name: Bondad 33-9 35
Location ID: 385734



Photo 4. Reference area comprised of pine, juniper, sagebrush and indian rice grass.