

Caerus Picenace LLC
Freedom Unit-62S97W 20SENE
Location ID: 335945



Entrance signs. Replace damaged or illegible signs.



As well signs are replaced additional information will be required

Caerus Picenace LLC
Freedom Unit-62S97W 20SENE
Location ID: 335945




Unused equipment



Rain caps missing

Caerus Picenace LLC
Freedom Unit-62S97W 20SENE
Location ID: 335945



Debris




Debris

Caerus Picenace LLC
Freedom Unit-62S97W 20SENE
Location ID: 335945



Production facility from Northeast corner of location



Production facility from Southeast corner of location

Caerus Picenace LLC
Freedom Unit-62S97W 20SENE
Location ID: 335945



Location from Northwest corner



Location from Northeast corner

Caerus Picenace LLC
Freedom Unit-62S97W 20SENE
Location ID: 335945



Location from Southeast corner



Location from Southwest corner