

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



As entrance signs are replaced additional information will be required

Random debris



Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



Random debris



Random debris

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712




Random debris



As wellhead signs are replace additional information will be required

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



Incorrect quarter/quarter section per ECMC database



Production and chemical tanks. Chemical pumps.

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



Production manifolds and separator building



Location from Southwest corner

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



Location from Southeast corner



Location from Northeast corner