

Inspection Photos
Location Name: Hung-Rasm TB
Location ID: 448676



Photo 1 – Tank Battery



Photo 2 – Tank Battery Sign



Inspection Photos
Location Name: Hung-Rasm TB
Location ID: 448676



Photo 3 – Heater Treaters



Photo 4 – ECD

Inspection Photos
Location Name: Hung-Rasm TB
Location ID: 448676



Photo 5 – Crude Oil Tanks




Photo 6 – Capacity Label