

Inspection Photos
Location Name: Shable PC GK 19-99HZ
Location ID: 416924



Photo 1 – Wellhead – Weeds



Photo 2 – ECD

Inspection Photos
Location Name: Shable PC GK 19-99HZ
Location ID: 416924



Photo 3 – Tank Battery



Photo 4 – Tank Battery Sign

Inspection Photos
Location Name: Shable PC GK 19-99HZ
Location ID: 416924



Photo 5 – Weeds around Tank Berm



Photo 6 – Heater Treater

Inspection Photos
Location Name: Shable PC GK 19-99HZ
Location ID: 416924



Photo 7 – Weeds at Gas Meter