

Inspection Photos
Location Name: Ranch 1
Location ID: 317622



Photo 1 – Wellhead



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Ranch 1
Location ID: 317622



**Photo 3 – Well Sign – Operator Name does not reflect
Current Operator**