

Inspection Photos

Location Name: PHIL WILSON-65N64W/19SWSE

Location ID: 323474



Photo #1

Phil Wilson 19-1 (123-13084) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 20 yds.



Photo #2

Phil Wilson 19-1, Mowery 19-2 Battery site

Abandoned: ALL Equipment Removed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources