

Inspection Photos

Location Name: MOWERY-65N64W/19SESE

Location ID: 328428



Photo #1

Mowery 19-2 (123-15978) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 200 yds.



Photo #2

Phil Wilson 19-1, Mowery 19-2 Battery site

Abandoned: ALL Equipment Removed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources