

Inspection Photos

Location Name: MUSTANG RESOURCES LLC BURNS 9-35-6-94 W Pad

Location ID: 324144



Photo # 6724 From entrance to location



Photo # 6725 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC BURNS 9-35-6-94 W Pad

Location ID: 324144



Photo # 6726 Location



Photo # 6727 Location



Inspection Photos

Location Name: MUSTANG RESOURCES LLC BURNS 9-35-6-94 W Pad

Location ID: 324144



Photo # 6728 Location



Photo # 6729 Tank not properly labeled/missing required information

Inspection Photos

Location Name: MUSTANG RESOURCES LLC BURNS 9-35-6-94 W Pad

Location ID: 324144



Photo # 6730 Tank not properly labeled/missing required information



Photo # 6731 Tank not properly labeled/missing required information