

Inspection Photos
Location: Bald Eagle 44-18
Facility ID: 307566



Photo 1 –Well Site Placard, Coordinates do not match ECMC records

Photo 2 – Wellhead

Inspection Photos
Location: Bald Eagle 44-18
Facility ID: 307566



Photo 3 – Bald Eagle 44-18 Offsite Pit Facility
119877

Photo 4 – Rig Anchor

Inspection Photos
Location: Bald Eagle 44-18
Facility ID: 307566



Photo 5 – Access road with Erosion