

Inspection Photos
Location: Bald Eagle 44-18 TR
Facility ID: 308346

Onsite Pit location



Photo 1 –Well Site Placard, Coordinates do not match ECMC records

Photo 2 – Wellhead

Inspection Photos
Location: Bald Eagle 44-18 TR
Facility ID: 308346



Photo 3 – Offsite Pit Facility ID 257988

Photo 4 – Offsite Pit Facility ID 257988

Inspection Photos
Location: Bald Eagle 44-18 TR
Facility ID: 308346



Photo 5 – Telemetry Equipment not working

Photo 6 – Erosion Along Access Road

Inspection Photos
Location: Bald Eagle 44-18 TR
Facility ID: 308346



Photo 7 – Erosion Along Access Road

Photo 8 – Erosion Along Access Road

Inspection Photos
Location: Bald Eagle 44-18 TR
Facility ID: 308346



Photo 9 – Erosion Along Access Road

