

**Inspection Photos**  
**Location: Tadpole 21-12**  
**Facility ID: 307609**



**Photo 1 –Well Site Placard**



**Photo 2 – Erosion in roadway**



**Inspection Photos**  
**Location: Tadpole 21-12**  
**Facility ID: 307609**



**Photo 3 – Exposed gathering line in road**



**Photo 4 – Erosion in roadway**



**Inspection Photos**  
**Location: Tadpole 21-12**  
**Facility ID: 307609**



**Photo 5 – Exposed gathering line**

**Photo 6 – Erosion in roadway**



**Inspection Photos**  
**Location: Tadpole 21-12**  
**Facility ID: 307609**



**Photo 7 – Erosion in Roadway**

