

Inspection Photos
Location: Bullsnake 34-1
Facility ID: 308021



Photo 1 –Well Site Placard

Photo 2 – Wellhead

Inspection Photos
Location: Bullssnake 34-1
Facility ID: 308021



Photo 3 – Pit

Photo 4 – Pit

Inspection Photos
Location: Bullsnake 34-1
Facility ID: 308021



Photo 5 – Erosion in roadway

Photo 6 – Erosion in roadway

Inspection Photos
Location: Bullssnake 34-1
Facility ID: 308021



Photo 7 – Erosion in Roadway

Photo 8 – Erosion in Roadway