

Castor 7-59 10 Pad

SWSE Section 10-T7N-R59W

Photo Documentation – Post-Cleanup

August 22, 2023

Prepared for





Wellhead and surrounding area. Drill rig and associated equipment was moved off location and the impacted secondary containment liner has been removed and properly disposed of.