



00063318

WELL SITE INSPECTION FORM

Well Name Coltharp A-2 API Number 05 - 103 - 09400
Operator Auraguest Permit # 890886
Location NENW 1-1N-102W County Rio Blanco
Field Rangely Inspector B. Macke

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) ☒ Fail(N) ☐ Date 6/21/91 ND ☐ DG ☐ WO ☐ PR ☐ SI ☐ TA ☐

=====

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES ☐ NO ☐ Returns _____
Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed ☐ Open ☐ Wellhead Installed: _____ Sign: Yes ☐ No ☐
Tank ID: Yes ☐ No ☐ N/A ☐ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes ☐ No ☐
Bradenhead Press: _____ Fluid: No ☐ Yes ☐ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____
Hole Plugged: Yes ☒ No ☐ Pits Backfilled: Yes ☒ No ☐
Material Buried: Yes ☒ No ☐ N/A ☐ Site Clean: Yes ☒ No ☐
Bond Release OK: Yes ☒ No ☐ Fed ☐ Hole Marker: Yes ☐ No ☒

Date of Safety/Status Inspection 6/21/91

Comments: Location cleared + leveled - deadman removed

Violations: Yes ☐ No ☒ Notice Sent: Yes ☐ No ☐ Date Sent: _____