



01092987

WELL SITE INSPECTION FORM

WELL NAME Coltharp A-2 API NUMBER 05 - 103 - 9400
OPERATOR Arquest PERMIT NUMBER 89-886
LOCATION NENW 1, 1N, 102W COUNTY Roblanco
FIELD Rangel - Marcos INSPECTOR KTB

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) _____ FAIL(N) _____ DATE _____ FN _____ FD ☒ WO _____

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? yes COMPLETION RIG/ACTIVITY Rig Stacked on location
DRILLING PITS: CLOSED _____ OPEN NA WELLHEAD SYSTEM INSTALLED NA
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____
MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____
BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS Cap welded on casing. 3 sections of 7" pipe on
location. Used bar ditch for pit.

Called 5/30/90 and told secretary that they need
well signs.