



## WELL SITE INSPECTION FORM

WELL NAME Calthorp A-2API NUMBER 05 - -OPERATOR Auraguest

PERMIT NUMBER \_\_\_\_\_

LOCATION 1-1N-101WCOUNTY Rio BlancoFIELD RangelyINSPECTOR SP

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) \_\_\_\_\_ FAIL(N) \_\_\_\_\_ DATE \_\_\_\_\_

FN \_\_\_\_\_ FD ☒ WO \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING DRILLING \_\_\_\_\_

CASING SIZE \_\_\_\_\_ DEPTH SET \_\_\_\_\_ CMT VOL \_\_\_\_\_ WOC \_\_\_\_\_

CONSISTENT WITH APD CASING PROGRAM? \_\_\_\_\_ RETURNS \_\_\_\_\_

RIG \_\_\_\_\_ BOP'S \_\_\_\_\_ CONTACT \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION \_\_\_\_\_

PIPE SET? \_\_\_\_\_ COMPLETION RIG/ACTIVITY \_\_\_\_\_

DRILLING PITS: CLOSED \_\_\_\_\_ OPEN \_\_\_\_\_ WELLHEAD SYSTEM INSTALLED \_\_\_\_\_

TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ WELL SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_

SKIM PIT: \_\_\_\_\_ gal TANKS: ( ) \_\_\_\_\_ bbls

EQUIPMENT \_\_\_\_\_

BRADENHEAD PRESSURE \_\_\_\_\_ FLUID: NO \_\_\_\_\_ YES \_\_\_\_\_ TYPE \_\_\_\_\_

METER RUN: YES \_\_\_\_\_ NO \_\_\_\_\_ WELL STATUS: PR \_\_\_\_\_ TA \_\_\_\_\_ SI \_\_\_\_\_ WELL CAT 3- \_\_\_\_\_

AL/PA/DA INSPECTION

DATE PLUGGED: \_\_\_\_\_ DATE PERMIT EXPIRED: \_\_\_\_\_

HOLE PLUGGED: YES \_\_\_\_\_ NO \_\_\_\_\_ PITS BACKFILLED: YES \_\_\_\_\_ NO \_\_\_\_\_

MATERIAL BURIED: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ SITE CLEAN: YES \_\_\_\_\_ NO \_\_\_\_\_

BOND RELEASE OK: YES \_\_\_\_\_ NO \_\_\_\_\_ FED \_\_\_\_\_ HOLE MARKER: YES \_\_\_\_\_ NO \_\_\_\_\_

DATE OF SAFETY/STATUS INSPECTION 6/27/90COMMENTS TA well - steel cap cover over surf pipe.No surface equipment - Well has sign