

# Inspection Photos

Loc: 308752

Operator: RED RIVER RANCH HOLDINGS LLC

Inspection Date: 11/15/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest along the access road which is stabilized and maintained.





## Inspection Photos



**Photo 2.** Facing south toward the reclaimed location. A uniform perennial vegetation cover has re-established.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:308752 | Date: 11/15/2023



## Inspection Photos



**Photo 3.** Facing southeast at the reclaimed location. A uniform perennial vegetation cover has re-established.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:308752 | Date: 11/15/2023



## Inspection Photos



**Photo 4.** Facing west at the reclaimed location.





## Inspection Photos



**Photo 5.** Facing northwest at the location.





## Inspection Photos



**Photo 6.** Facing northeast at the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:308752 | Date: 11/15/2023



## Inspection Photos



**Photo 7.** Facing northeast at the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:308752 | Date: 11/15/2023