

Inspection Photos

Loc: 308753

Operator: RED RIVER RANCH HOLDINGS LLC

Inspection Date: 11/15/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road which remains per approved variance. The rod is stabilized and BMP's are maintained..



Inspection Photos



Photo 2. Facing northeast along the access road which is stabilized and maintained.



Inspection Photos



Photo 3. Facing north along the access road which is stabilized and maintained.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:308753 | Date: 11/15/2023

Inspection Photos



Photo 4. Facing east toward the reclaimed location.



Inspection Photos



Photo 5. Facing southeast at the location. A uniform perennial vegetation cover has re-established.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:308753 | Date: 11/15/2023

Inspection Photos



Photo 6. Facing southeast along the fill slope of the location. A uniform perennial vegetation cover has re-established.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:308753 | Date: 11/15/2023

Inspection Photos



Photo 7. Facing northwest at the location.

