

Inspection Photos

Loc: 322277

Operator: **CINNAMON CREEK OIL & GAS INC**

Inspection Date: 11/08/2023

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the tank battery. It looks like the capacity has been posted on from of tank 100BBL.



Inspection Photos



Photo 2. The wires are still exposed on electric breaker box which is a safety issue. Grass was mowed inside the containment but should also be raked up and removed.



Inspection Photos



Photo 3. Facing toward the well. It appears soils was scooped up at red arrow to cover oil stained soil at the wellhead. The oil stained soils need to be cleaned up and properly disposed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322277 | Date: 11/08/2023

Inspection Photos



Photo 4. Facing toward the wellhead. Dirt has been placed over the stained soils at wellhead.



Inspection Photos



Photo 5. It appears soils were also shoveled over the oil at the pumpjack that was previous written up. The oil stained soils need to be cleaned up and properly disposed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:322277 | Date: 11/08/2023

Inspection Photos



Photo 6. Facing east toward the access. Operator must ensure vehicle aren't tracking mud onto landowners graveled area.

