

Inspection Photos

Loc: 309279

Operator: RED RIVER RANCH HOLDINGS LLC

Inspection Date: 11/15/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the pre-existing access road.



Inspection Photos



Photo 2. Facing south along the pre-existing access road. Stormwater BMP's along the road are maintained.



Inspection Photos



Photo 3. Facing west toward the location which is stabilized with perennial vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309279 | Date: 11/15/2023

Inspection Photos



Photo 4. Facing southwest at the reclaimed location. The location is stabilized and vegetation cover has established to surrounding reference area levels.



Inspection Photos



Photo 5. Facing west at the reclaimed location. The location is stabilized and vegetation cover has established to surrounding reference area levels.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309279 | Date: 11/15/2023

Inspection Photos



Photo 6. Facing southwest along the cut slope of the location. The location is stabilized and vegetation cover has established to surrounding reference area levels.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309279 | Date: 11/15/2023

Inspection Photos



Photo 7. Facing southeast along the cut slope of the location. The location is stabilized and vegetation cover has established to surrounding reference area levels.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309279 | Date: 11/15/2023