

Inspection Photos

11/14/2023

Operator: CAERUS PICEANCE LLC #10456

Location ID: 479149

Inspection Doc: 696205426

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 479149



Photo 1: Tanks on the west end of the Location. Hatches open at tanks.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 2: Trash, debris and/or unused equipment improperly stored on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 3: Trash, debris and/or unused equipment improperly stored on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 4: Trash, debris and/or unused equipment improperly stored on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 5: Photo taken from the fill slopes on the west end of the Location. Photo shows trash, debris and/or unused equipment improperly stored on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 6: Photos show chemical containers improperly stored on the working pad surface. Some containers observed to empty and is considered trash/debris.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 7: Photos show chemical containers improperly stored on the working pad surface. Some containers observed to empty and is considered trash/debris.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 8: Photos taken from the west end of the Location, facing north. Photo shows BMPs to stabilize, as well as to minimize erosion, degradation and sediment transport at the topsoil stockpiles and fill slopes are no longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 9: Photos taken from the west end of the Location. Photo shows BMPs to stabilize, as well as to minimize erosion, degradation and sediment transport at the topsoil stockpiles are no longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 10: Photos taken from the west end of the Location. Photo shows erosion logs are no longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 11: Photos taken from the west end of the Location. Photo shows erosion logs are no longer in proper functioning condition..



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 12: Photos taken from the west end of the Location. Photo shows erosion logs are no longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 13: Photos taken from the north end of the Location. Photo shows erosion logs are no longer in proper functioning condition. Photo also shows BMPs to minimize erosion, degradation and sediment transport at the topsoil stockpiles are no longer in proper functioning condition; hydromulch has degraded



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 14: Photos taken from the north end of the Location. Photo shows erosion logs are no longer in proper functioning condition. Photo also shows BMPs to minimize erosion, degradation and sediment transport at the topsoil stockpiles are no longer in proper functioning condition; hydromulch has degraded



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources