

Inspection Photos
Location Name: HOWARD USX A/09-19
Location #: 423200



Photo #1

Howard USX A 09-19 (123-33520) Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plugs



Photo #2

Howard USX A 09-19 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plugs
Site safety signage




Inspection Photos
Location Name: HOWARD USX A/09-19
Location #: 423200



Colorado Energy & Carbon Management Commission
 Weld County
 +1 48-5032999 - 104-545709
 353° N
 2023-11-16 15:04

Photo #3
Howard USX A 09-1 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plugs
Wellsite entrance



Colorado Energy & Carbon Management Commission
 Weld County
 +1 48-5032999 - 104-5596688
 353° N
 2023-11-16 14:51

Photo #4
Howard USX A 09-19 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plugs
JSA: 2023-11-16

