

Interim Reclamation and Stormwater Inspection

Date: 11/02/2023

Operator: PDC Energy Inc. - 69175

Location ID: 329884

Inspection Document #: 713900093

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: WEISS 1-34
Location ID: 329884



Photo 1. The photo was taken on the tank battery location facing South. The photo illustrates the location sign.

Photo 2. The photo was taken on the South side of the tank battery location facing North. The photo illustrates erosion creating rills in the road mix pad.

Inspection Photos
Location Name: WEISS 1-34
Location ID: 329884



Photo 3. The photo was taken on the South side of the tank battery location facing Southeast. The photo illustrates sediment from Photo 2 being carried downslope and over straw wattle at the edge of the location. The photo also illustrates kochia growing all along the edge of the location.



Photo 4. The photo was taken on the tank battery location facing Northeast. The photo illustrates rilling across the pad as well as Scotch thistle growing at the location tank battery.

Inspection Photos
Location Name: WEISS 1-34
Location ID: 329884



Photo 5. The photo was taken at the South side of the tank battery location facing Northeast. The photo illustrates large amounts of rilling and undesirable vegetation.