

Inspection Photos
Location: Liberty 32-32
Facility ID: 415957



Photo 1 – Well Site Placard

Photo 2 – Tank Battery

Inspection Photos
Location: Liberty 32-32
Facility ID: 415957



Photo 3 – Tank Battery

Photo 4 – Wellhead

Inspection Photos
Location: Liberty 32-32
Facility ID: 415957



Photo 5 – Stained soil

Photo 6 – Oil staining on Pumping Unit base.

Inspection Photos
Location: Liberty 32-32
Facility ID: 415957



Photo 7 – Evidence of oil leak on Pumping unit, Unit appears to be down for maintenance

Photo 8 – Machine Guarding, Unit appears to be down for maintenance at the time of inspection.