

Inspection Photos
Location: Royal Gorge 8
Facility ID: 322246



Photo 1 –Well Site Placard



Photo 2 – Tank Battery

Inspection Photos
Location: Royal Gorge 8
Facility ID: 322246



Photo 3 – Dripping valve on truck load out

Photo 4 – Dripping valve



Inspection Photos
Location: Royal Gorge 8
Facility ID: 322246



Photo 5 – Tank battery



Photo 6 – Wellhead

Inspection Photos
Location: Royal Gorge 8
Facility ID: 322246



Photo 7 – Oil observed on wellhead equipment.



Photo 8 – Rig Anchor. Anchor should have a permanent marker.



Inspection Photos
Location: Royal Gorge 8
Facility ID: 322246



Photo 9 – Access Road.

