

Inspection Photos
Location: Slanovich 32-1
Facility ID: 322227




Photo 1 – Well Site Placard

Photo 2 – Drill Cuttings

Inspection Photos
Location: Slanovich 32-1
Facility ID: 322227



Photo 3 – Drill Cuttings and Tank

Photo 4 – Drill Cuttings

Inspection Photos
Location: Slanovich 32-1
Facility ID: 322227



Photo 5 – Location Looking east, weeds

Photo 6 – Fill Slope of location, BMPs/Wattles

Inspection Photos
Location: Slanovich 32-1
Facility ID: 322227



Photo 7 – Erosion on west side of location

Photo 8 – Erosion along Road Leading to location

Inspection Photos
Location: Slanovich 32-1
Facility ID: 322227



Photo 9 – Tank Battery Load Out

Photo 10 – Access Road