

Inspection Photos

Location ID/Name: 481859, UPRR 42 PAN AM-63N66W 29NWSW TB



Photo 1
Battery



Photo 2
Discarded Tire



Photo 3
ECD



Photo 4
Production Equipment



Photo 5
Pig Station



Photo 6
Separator