

**BEEMAN OIL & GAS INC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311768**



**BEEMAN OIL & GAS INC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311768**



Barrel at pump jack is not labeled.



Secondary containment is full of spilled fluid.

**BEEMAN OIL & GAS INC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311768**



**Five gallon bucket not stored in
containment. Oil leak spillage from engine.**

**BEEMAN OIL & GAS INC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311768**



Unused 1" riser at separation equipment.



Unused 1" riser at separation equipment.