

**Operator: 8 NORTH LLC**

**Location Name: SHABLE 3-32, Trostel 32-33,34**

**Loc ID: 464515**

**Inspection: 696305422**



Exhibit A

**CA:** Recycle Pump Guard in disrepair. Comply with Rule 606.

**CA Resolution:** Pump Guard has been recycled to comply with Rule 606.