

Operator: EXTRACTION OIL & GAS
Location Name: Hung-Rasm TB Location
Loc ID: 448676
Inspection: 696305410



Exhibit A

CA: North Crude Oil Tank - Capacity Label has faded no longer visible. Install sign to comply with Rule 605.h.

CA Resolution: Sign has been installed to comply with Rule 605.h.