

Operator: 8 NORTH LLC

Location Name: BVW 31-13 & Kaleo 1, 16-31

Loc ID: 460841

Inspection: 696305420



Exhibit A

CA: Recycle Pump Guard in disrepair. Comply with Rule 606.

CA Resolution: Pump Guard has been repaired to comply with Rule 606.