

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad**  
**Location ID: 335272**



**Location Overview: Location is within High Priority/Density  
Habitat areas. Location is approximately 61 yards from a  
creek/drainage that contributes to the Colorado River.**

**Section/Township/Range: 20 6S94W**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad**  
**Location ID: 335272**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad**  
**Location ID: 335272**



**Photo # 7225 Tunnel erosion**



**Photo # 7226 Erosion & transport of sediment off location**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad**  
**Location ID: 335272**



**Photo # 7227 Erosion & transport of sediment off location**

**Photo # 7228 Erosion & transport of sediment off location**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad**  
**Location ID: 335272**



**Photo # 7229 Erosion & transport of sediment off location**



**Photo # 7230 Erosion & transport of sediment off location**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad**  
**Location ID: 335272**



**Photo # 7231 Erosion & transport of sediment off location**



**Photo # 7232 Erosion & transport of sediment off location**