

Inspection Photos
Location Name: Tillie 1-3-OWP
Location ID: 331254



Photo 1 – Location Overview – Production Equipment has been removed



Photo 2 – Location Overview – Production Equipment has been removed

Inspection Photos
Location Name: Tillie 1-3-OWP
Location ID: 331254



Photo 3 – Gas Line



Photo 4 – Wellhead Overview

Inspection Photos
Location Name: Tillie 1-3-OWP
Location ID: 331254



Photo 5 – Wellhead



Photos 6 – Wellhead