

Inspection Photos
Location Name: Einsenhaur 1-3-OWP
Location ID: 331352



Photo 1 – Wellhead



Photo 2 – Wellhead

Inspection Photos
Location Name: Einsenhaur 1-3-OWP
Location ID: 331352



Photo 3 – Gas Line and Well Sign



Photo 4 – Location Overview – Production Equipment has been removed

Inspection Photos
Location Name: Einsenhaur 1-3-OWP
Location ID: 331352



Photo 5 – Location Overview – Production Equipment has been removed