

Inspection Photos

Location Name: HOWARD USX A-66N64W/9NESW

Location #: 306350



Colorado Energy & Carbon Management Commission
Weld County
+40.499555 -104.556913
205° SW
2023-11-22 11:36



Colorado Energy & Carbon Management Commission
Weld County
+40.499555 -104.556913
201° W
2023-11-22 11:36

Photo #1

Howard USX A 9-11 (123-24496) Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)

Photo #2

Howard USX A 9-11 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)
Site safety signage



Inspection Photos
Location Name: HOWARD USX A-66N64W/9NESW
Location #: 306350



Photo #3

Howard USX A 9-11 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)
Wellsite entrance



Photo #4

Howard USX A 9-11 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)
JSA: 2023-11-22



Inspection Photos

Location Name: HOWARD USX A-66N64W/9NESW

Location #: 306350



Photo #5

Howard USX A 9-11 Battery site

Plugging & Abandoned | PA

Plugging Ops; Cementing: Initial plug(s)

Battery sign



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources