

Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY RMV 115-4 Pad

Location # 324084



Photo # 7659 From entrance to location



Photo # 7660 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY RMV 115-4 Pad

Location # 324084



Photo # 7661 Location



Photo # 7662 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY RMV 115-4 Pad

Location # 324084



Nov 27, 2023 at 12:07:26 PM
CO

Photo # 7663 Unmarked deadman



Nov 27, 2023 at 12:07:20 PM
CO

Photo # 7664 Same unmarked deadman