


Inspection Photos

Location Name: PUBLIC SERVICE COMPANY OF COLORADO, ASBURY STORAGE UNIT-FED #9

Location ID: 312382

Date: 11/21/2023



Nov 21, 2023 at 16:52:52
Grand Junction CO 81505
United States



Nov 21, 2023 at 16:53:44
Grand Junction CO 81505
United States

Location Entrance – Photo #07576

Wellhead – Photo #07578

Inspection Photos

Location Name: PUBLIC SERVICE COMPANY OF COLORADO, ASBURY STORAGE UNIT-FED #9

Location ID: 312382

Date: 11/21/2023



Separator/Tank – Photo #07577



No Secondary Containment – Photo #07581

Inspection Photos

Location Name: PUBLIC SERVICE COMPANY OF COLORADO, ASBURY STORAGE UNIT-FED #9

Location ID: 312382

Date: 11/21/2023

Nov 21, 2023 at 16:55:24
Grand Junction CO 81505
United States



**Rill Erosion Transporting Sediment Off Location – Photo
#07579**