

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 312598

Date: 11/22/2023



Location Entrance – Photo #07590



Wellhead/Weeds – Photo #07591

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 312598

Date: 11/22/2023



Separator/Gas Meter/Weeds – Photo #07593



Tank Battery/Weeds – Photo #07594

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 312598

Date: 11/22/2023



Trash/Debris – Photo #07598



Trash/Debris – Photo #07599

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 312598

Date: 11/22/2023



**Insufficient Erosion Control/Rill Erosion on Access Road –
Photo #07600**