

Work Completion Report

Contractor: Jamm Power Services

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
KELLY 1A (2023 Seasonal)	Fall	Jamm Power	11/01/2023
Work Summary		Reclamation Type	Land Use
Inspected site. Pulled noxious weeds, placed in contractor bags, removed and disposed bags and debris. Rancher is using site to feed cattle mineral licks.		Final Maint	Pasture
One-Call Number	Red Zone Rep	Red Zone Date	

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance	Normal	No	Location(s): KELLY 1A Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: **43,560 sq ft**
Seed Mix: **None used**
Crop Type:
Soil Type: **Clay Loam**
Stabilization Date:
Seeding Date:
Mulch: **None**
Straw Bales: **NA**
Soil Amendment Type: **None**
Soil Amendment Rate: **NA**
Imported Top Soil: **NA**
Top Soil Source: **NA**
General Notes:

LOCATION INFO

Location(s) – Name: KELLY 1A

COGCC ID: **318739**
Well APIs at Location: **12309848**
Land Rep: **None established**
Land Owner:
Rec Contractor PO(s): **Jamm Power PO:4501167939**
Vendor PO(s): **Buffalo Brand Seed PO:4501173751**
Billing Notes: **O22-00638.01.10**
Legal Address: **(WELD) NESW 7 2N66W**
Topsoil Source:
Variance Notes:
Private Utility Notes:
Wildlife Restrictions:
General Notes:
COGCC Doc #'s:
Initial Reclaim Complete Date:
Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Site Map
Description:



Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: SO access reference

Description:



Photo Name: Access and livestock reference

Description:



Photo Name: Well site facing north

Description:



Photo Name: Well site facing west

Description:



Photo Name: Well site facing south

Description:



Photo Name: Well site facing east

Description:

