

# Inspection Photos

Loc: 309290

Operator: RED RIVER RANCH HOLDINGS LLC

Inspection Date: 11/15/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south along the pre-existing access road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:309290 | Date: 11/15/2023



## Inspection Photos



**Photo 2.** Facing southeast along the pre-existing access road.





## Inspection Photos



**Photo 3.** Facing southeast along the pre-existing access road.





## Inspection Photos



**Photo 4.** Facing southwest at the reclaimed location. The location is stabilized with perennial vegetation cover.



## Inspection Photos



**Photo 5.** Facing southwest at the reclaimed location. The location is stabilized and vegetation cover has established to surrounding reference area levels.





## Inspection Photos



**Photo 6.** Facing southwest along the fill slope of the location. The location is stabilized and vegetation cover has established to surrounding reference area levels.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:309290 | Date: 11/15/2023



## Inspection Photos



**Photo 7.** Facing at the location. The location is stabilized and vegetation cover has established to surrounding reference area levels.

