

Inspection Photos

Loc: 386512

Operator: MERIDIAN OIL INC

Inspection Date: 11/17/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the reclaimed location. The perennial vegetation is well-established throughout the location.



Inspection Photos



Photo 2. Facing east at the location.



Inspection Photos



Photo 3. Facing east along the upper slope. The erosion wattles will need to be removed for final reclamation.



Inspection Photos



Photo 4. South side at top of the slope facing northwest. The perennial vegetation is well-established throughout the location.



Inspection Photos



Photo 5. Facing toward the east side of the location. There is less vegetation in this area but the area appears to be stabilized.



Inspection Photos



Photo 6. Facing toward the upper center of the location. This area approximately 15'x15' has less vegetation cover. The erosion wattles will need to be removed for final reclamation.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:386512 | Date: 11/17/2023