

Inspection Photos
Location Name: Sarafini B 2
Location ID: 318614



Photo 1 Location.

Photo 2 Dead undesirable vegetation around the WH sign.

Inspection Photos
Location Name: Sarafini B 2
Location ID: 318614



Photo 3 Dead undesirable vegetation around the WH .



Photo 4 Dead undesirable vegetation around the Pump jack.

Inspection Photos
Location Name: Sarafini B 2
Location ID: 318614



Photo 5 Ancillary equip.



Photo 6 Dead undesirable vegetation around the Pump jack.