

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 72-34 Pad

Location ID: 323994



Photo # 7570 From entrance to location




Photo # 7571 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 72-34 Pad

Location ID: 323994



Photo # 7572 Location



Photo # 7573 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 72-34 Pad

Location ID: 323994



Photo # 7574 Location



Photo # 7575 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 72-34 Pad

Location ID: 323994



Photo # 7007 From inspection 708902256 conducted on 11/16/2023 Open ended load line



Photo # 7576 Open ended load line