

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/7NWSE

Location ID: 323851

Date: 11/22/2023



Location Entrance – Photo #07618



Wellhead – Photo #07619

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/7NWSE

Location ID: 323851

Date: 11/22/2023



Separator/Weeds – Photo #07622



Tank Battery/Weeds – Photo #07624

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/7NWSE

Location ID: 323851

Date: 11/22/2023



Unused Equipment Stored on Location/Weeds – Photo #07620



Antifreeze Stored on Location (No NFPA label or secondary containment) – Photo #07623