

Final Reclamation Inspection

November 10th, 2023

Operator: Simcoe LLC - 10749

Location ID: 333832

Inspection Document #: 714000131

La Plata County, CO

Township: SWNE 8 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WIRT E 1, F 1
Location ID: 333832



Photo 1. View of the disturbance taken from the entrance facing center.
Note: two wells share this location

Inspection Photos
Location Name: WIRT E 1, F 1
Location ID: 333832



11/10/23
+37.034396,-107.628481
39° NE

Photo 2. View of the eastern interim reclamation area facing northeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07868, 05131



Photo 3. View of the undesirable vegetation within the center of the disturbance. This is considered debris and needs to be removed.



Inspection Photos
Location Name: WIRT E 1, F 1
Location ID: 333832



Photo 4. Reference area comprised of sagebrush, rabbit brush and squirrel tail.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07868, 05131

Inspection Photos
Location Name: WIRT E 1, F 1
Location ID: 333832



Photo 5. Reference area comprised of sagebrush, rabbit brush and squirrel tail.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07868, 05131