

Final Reclamation Inspection

November 20th, 2023

Operator: Enduring Resources LLC - 10663

Location ID: 326359

Inspection Document #: 714000146

La Plata County, CO

Township: SENE 5 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: La Posta 3R
Location ID: 326359



11/20/23
+37.135650,-107.951956
223° SW



11/20/23
+37.135650,-107.951956
197° S

Photo 1. View of the project area taken from the entrance facing center.

Inspection Photos
Location Name : La Posta 3R
Location ID: 326359



Photo 2. View of the erosional channel that remains along the access road. Stormwater BMPs installed are not functioning.

Inspection Photos
Location Name : La Posta 3R
Location ID: 326359



Photo 3. Rill erosion observed in the northern interim reclamation area at the base of the cut slope.

Inspection Photos
Location Name : La Posta 3R
Location ID: 326359



Photo 4. View of wattles that are not installed properly installed in the western interim reclamation area.

Inspection Photos
Location Name : La Posta 3R
Location ID: 326359

11/20/23
+37.135124,-107.952233
28° NE



Photo 5. View of the eastern interim reclamation area facing northeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name : La Posta 3R
Location ID: 326359

11/20/23
+37.135424,-107.950397
117° SE



Photo 6. Reference area comprised of smooth brome, sagebrush and rabbit brush.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515