

Final Reclamation Inspection

November 20th, 2023

Operator: Enduring Resources LLC - 10663

Location ID: 326631

Inspection Document #: 714000147

La Plata County, CO

Township: NENW 5 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: La Posta 5-1
Location ID: 326631



Photo 1. View of the project area taken from the entrance facing center.



Inspection Photos
Location Name : La Posta 5-1
Location ID: 326631



Photo 2. Large erosion feature observed on the disturbance.
Approximately 3 feet deep.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515



Photo 3. View of the northern interim reclamation area facing northwest.



Inspection Photos
Location Name : La Posta 5-1
Location ID: 326631



Photo 4. Reference area comprised of pine, sagebrush and crested wheatgrass.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515