

Final Reclamation Inspection

November 1st, 2023

Operator: BP America Production Company -
10000

Location ID: 325562

Inspection Document #: 714000127

La Plata County, CO

Township: SESW 30 33N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hot 30-02 1
Location ID: 325562



Photo 1. View of the project area taken from the southern edge facing north. Photos shows that the southern edge of the project area shows no vegetation establishment with exposed bare soils.

Inspection Photos
Location Name: Hot 30-02 1
Location ID: 325562



Photo 2. View of the northern edge of the project area that appears consistent with the adjacent reference area.

Inspection Photos
Location Name: Hot 30-02 1
Location ID: 325562



Photo 3. View of the reference area comprised of intermediate wheatgrass, rabbit brush and crested wheatgrass.