

Final Reclamation Inspection

November 10th, 2023

Operator: BP America Production Company -
10000

Location ID: 333610

Inspection Document #: 714000134

La Plata County, CO

Township: NWNW 35 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Briggs A 1
Location ID: 333610



Photo 1. View of the project area taken from the southern edge facing center.

Inspection Photos
Location Name: Briggs A 1
Location ID: 333610



Photo 2. Cardinal photos taken from the middle of the project area. Left photo facing north, right photo facing east. Note: musk thistle observed in the rosette stage on the location. Approximately 50 individuals.

Inspection Photos
Location Name: Briggs A 1
Location ID: 333610



Photo 3. Cardinal photos taken from the middle of the project area. Left photo facing south, right photo facing west. Note: Large bare patches of exposed soil observed in the southern and western portions of the project area that required additional reclamation.

Inspection Photos
Location Name: Briggs A 1
Location ID: 333610



Photo 4. Reference area comprised of juniper, sage brush and smooth brome.